

Buncombe County Solid Waste Management Facility
Subtitle D Landfill
Settlement Plate Monitoring Data - Summary

Settlement Plates	Total Settlement
	(inches)
SP-1	6.12
SP-2	8.64
SP-3	6.84
SP-4	6.60
SP-5	3.96
SP-6	4.08
SP-7	11.76
SP-8	9.36
SP-9	23.16
SP-10	11.64

From January 2006 to October 2011